Notes

The following **Tech Update** highlights the process for updating the firmware on the **MDR2.0**.

Step by Step Process

1) Copy the file stm8.s19 to an empty USB flash/jump drive that is formatted to a FAT32

2) Turn vehicle on and turn radio on

3) Once radio has gone through boot up, plug USB jump drive in

4) The radio will display "UPG MCU" and will shut off after about 2 minutes (When radio shuts off, the firmware has been installed)

5) With radio off, remove the USB flash/jump drive and disconnect the B+ wire (Yellow) and ACC wire (Red) from the back of the radio

6) Reconnect the B+ wire (Yellow) and the ACC wire (Red) on the back of the radio then turn radio on

7) Press "MODE" button to "AUX" source then press and hold the ">>I" button for 5 seconds and "RESET" will be displayed (the firmware installation is complete)

8) To confirm that the new firmware has been installed, press "MODE" button to "AUX" source (press and hold "I<<" button for 5 seconds and will show the software version)

9) If it is "210802U1," then the latest version has been installed